ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: M119549 Client: Alaskan Copper Works PO M119549, F&BI 805141 Date Received: 05/15/08 Project: Date Extracted: 05/15/08 Lab ID: 805141-01 x10 Date Analyzed: 05/16/08 Data File: 805141-01 x10.040 Matrix: Water Instrument: ICPMS1 Units: Operator: ug/L (ppb) hr

Lower Upper Internal Standard: Limit: % Recovery:

Limit: 60 125 Germanium 89

Concentration Analyte: ug/L (ppb) 1,300 Chromium Nickel 1,550 Copper 1,310 Zinc < 50

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank Client: Alaskan Copper Works Date Received: PO M119549, F&BI 805141 Not Applicable Project: Date Extracted: 05/15/08 Lab ID: I8-182 mb Date Analyzed: 05/16/08 Data File: I8-182 mb.020 ICPMS1 Matrix: Water Instrument:

Units: ug/L (ppb) Operator: hr

Lower Upper Internal Standard: % Recovery: Limit: Limit:

Internal Standard: % Recovery: Limit: Limit: Germanium 91 60 125

Concentration
Analyte: ug/L (ppb)

Chromium <1

 Nickel
 <1</td>

 Copper
 <1</td>

 Zinc
 <5</td>

ENVIRONMENTAL CHEMISTS

Date of Report: 05/20/08 Date Received: 05/15/08

Project: Metro Self Monitor, PO M119549, F&BI 805141

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 805130-01 (Duplicate)

		Sample	Duplicate	Relative Percent	Acceptance
Analyte	Reporting Unit	s Result	Result	Difference	Criteria
Chromium	ug/L (ppb)	<1	<1	nm	0-20
Nickel	ug/L (ppb)	2.62	2.63	0	0-20
Copper	ug/L (ppb)	1.04	<1	nm	0-20
Zinc	ug/L (ppb)	8.78	<5	nm	0-20

Laboratory Code: 805130-01 (Matrix Spike)

	Analyte	Reporting Units	s	Spik Leve	20	Sample Result	Rec	rcent overy AS	Acceptance Criteria		
•	Chromium	ug/L (ppb)		20	Test.	<1		92	50-150		
	Nickel	ug/L (ppb)		20		2.62		82	50-150		
in.	Copper	ug/L (ppb)		20		1.04		80	50-150		
	Zinc	ug/L (ppb)		50		8.78		56	50-150		

Laboratory Code: Laboratory Control Sample

			Spike	Percent Recovery		э .
1	Analyte	Reporting Units	Level	LCS	Criteria	
à.	Chromium	ug/L (ppb)	20	103	70-130	
	Nickel	ug/L (ppb)	20	97	70-130	
	Copper	ug/L (ppb)	20	100	70-130	
	Zinc	ug/L (ppb)	50	72	70-130	

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probablility.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

May 20, 2008



INVOICE # 08ACU0520-1

Accounts Payable Alaskan Copper Works 628 South Hanford Seattle, WA 98134

RE: Project Metro Self Monitor, PO M119549, F&BI 805141 - Results of testing requested by Gerry Thompson for material submitted on May 15, 2008.

FEDERAL TAX ID #(b) (6)

805141					//	NOF C	051	roi	JΥ	M	E	Q	1/15	5/0	18			HI	φ
Sand Banart To (78091)	Thom	050)		SAMPL	EPS (s	ignature)											age#_	AROUND	of
Send Report To GERALD THOMPSON Company ALASKAN Copper Works					PROJECT NAME/NO. PO #											Stan	dard	(2 Weeks)	
			METRO SECT MONITOR M119549											RUSH & Cay Rush charges authorized by:					
Address 628 S. Hendord St																			
City, State, ZIP SeATTLE UA 78134			34	REMARKS SAMPLE DISPOSAL □ Dispose after 30 days															
Phone # 206-571-602			- 1											1				mples vith instru	
Phone #_ 228 37. 228	<u>⊘</u> rax #	- 302	1007												L		can w	in instru	ictions —
			r	T	ANALYSES REQUESTED														
· ·							lei	ine	21E	260	8270		10						
Sample ID	Lab ID	Date	Time	Sample	Tone	# of	Dies	aso	BTEX by 8021B	VOCs by 8260	by 8	HFS	\$1	`				N ₀	otes
Dample 1D	Dab 1D	Date	Time	Campic	Турс	containers	TPH-Diesel	TPH-Gasoline	3X b	Cs]	SVOCs by	Ħ	(3)					1	10103
							Ţ	TP	BTJ	2	SV	Ì	200	•					
m119549	01	5/15/08	12:3	HZ	\overline{a}	1							人						
1.0000	+	710/08	1430	NC		- (6.						-		 			
	<u> </u>	ļ		<u> </u>													_		
					*														
	26																		
				 													 	<u> </u>	
				<u> </u>												_	-		
																 	-	<u> </u>	
		<u> </u>				 	-	<u> </u>				-		, - -	_	-	┼		
	<u></u>	1		1			<u>L</u>				<u> </u>					<u></u>	<u> </u>	<u> </u>	
Friedman & Bruya, Inc. 3012 16th Avenue West	Relinquished b	SIGNATU y:	RE		7	PRINT	7				\dashv		$\frac{\text{CC}}{2}$	MP	ANY	-	ا ا	DATE	TIME
Seattle, WA 98119-2029	XXX	99			TE	/	01	0	20~)	\dashv	_/	T	<u>~</u>	, 		4	15/08	2:46 p
	Received by Relinquished b	y/a	W	Whan than Feb.						B1		·	<u> </u> S	115/08	d.40				
Ph. (206) 285-8282	,	71				· · · · · · · · · · · · · · · · · · ·	,,	·			_								
Fax (206) 283-5044	Received by:																		
FORMS\COC\COC.DOC	4) 10			, , , , , , , , , , , , , , , , , , ,														0//	

Samples received at 24 °C

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

May 20, 2008

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on May 15, 2008 from the Metro Self Monitor, PO M119549, F&BI 805141 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you should have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0520R.DOC